

Environmental Defense Institute
Troy, Idaho 83871-0220
<https://environmental-defense-institute.org>

Mackay Dam: A Preventable Disaster

Attached are pictures of Mackay Dam infrastructure taken by Idaho Department of Water Resources Inspectors and attached to these reports:

1. State of Idaho Department of Water Resources, Record of Inspection, Mackay Dam, File No. 34-2225, Date 8/6/09.
2. State of Idaho Department of Water Resources, Record of Inspection, Mackay Dam, File No. 34-2225, Date 9/13/11.
3. State of Idaho Department of Water Resources, Record of Inspection, Mackay Dam, File No. 34-2225, Date 3/27/13.
4. Dam Safety Section, Trip Report, To: Kade Raymond, From: John Falk, PE. 12/4/13, IDWR File: 34-2225, Mackay Dam Outlet Inspection.
5. State of Idaho Department of Water Resources, Record of Inspection, Mackay Dam, File No. 34-2225, Date 8/11/15.